

**Recent Repair, Maintenance and Update Data for 1985 Fiero GT ...
Vin Number 1G2PG3790FP268597**

Date	Mileage	Description	Cost	Performed by
04/2007	50,000	New: rear brake pads/ rotors/ and both disks resurfaced / new parking brake cable installed	\$550	Davis Auto Care
04/2007	51,000	New alternator installed	\$401	Davis Auto Care
05/2007	51,500	New High Capacity Battery Installed with 3 year replacement warranty	\$85	Owner Installed
04/2008	54,000	Installed New Stainless Steel Cat Converter and Borla Stainless Steel High Performance Exhaust System (from Fiero Store)	\$900	Local Muffler Shop installed the system; good for ~ 7 HP according to Borla
04/2008	54,000	Oil change with 5-40 full synthetic motor oil / installed triple volume high capacity oil filter / greased all suspension fittings	\$50	Owner Installed
04/2009	57,000	New: spark plugs / high performance plug wires / coil / and electronic ignition module	\$150	Owner Installed : car now runs better than stock
05/2009	58,000	Installed Hypertech: High Performance Ignition Chip, 175 deg. Fan switch, and 160 deg. Thermostat (all from Fiero Store)	\$200	Owner Installed : car runs significantly better and much cooler. No more running close to engine temp red zone on very hot days; adds ~8 HP.
05/2009	59,500	New Ferrari style aluminum wheels / tires /struts / shocks / front suspension components / and alignment front and rear	\$1132	Bell Tire package deal: took ~\$400 off total of individual prices
11/2009	60,000	New High Capacity Battery Installed replaced under warranty	\$0	Owner Installed
04/2010	60,773	New air conditioning condenser / had rest of system rebuilt and converted to R134 refrigerant	\$1,316	Davis Auto Care
06/2012	61,500	Installed K & N air filter / oil change with 5-40 full synthetic motor oil / installed triple volume high capacity oil filter / greased all suspension fittings	\$80	Owner Installed : K & N air filter along with Borla exhaust and new ignition parts improved performance

**Recent Repair, Maintenance and Update Data for 1985 Fiero GT ...
Vin Number 1G2PG3790FP268597**

Date	Mileage	Description	Cost	Performed by
06/2012	61,500	New drivers side seat belt – safety update (Fiero Factory)	\$259	Owner Installed
06/2012	61,500	New interior headliner / visors / sun roof seals / detailed rest of interior (parts from Fiero Factory)	\$350	Owner Installed : interior now looks like new
05/2015	63,000	Cleaned and re-oiled K & N air filter / oil change with 5-40 full synthetic Mobile One motor oil / installed triple volume high capacity oil filter / new muffler clamps / greased suspension fittings	\$95	Owner Installed
05/2015	63,000	Installed two Paul Vargas rebuilt headlight motors and lubed lighting system rotating components / also realigned headlights	\$143	Owner Installed
05/2015	63,000	Installed new head light relays / fixed interior headlight switch and installed lights-up cut-off switch to save headlight motors from future wear (also functions as safety item when working near headlights)	\$100	Owner Installed
05/2015	63,300	New front brake calipers and pads / resurfaced front disks / repacked front wheel bearings / new brake fluid / and had whole braking system checked (all to spec.)	\$615	Hal's Auto Service
10/2015	64,014	Car fully detailed: interior, front compartment, engine, underbody and exterior (exterior paint cleaned, prepped, clay bared, waxed and buffed)	\$100	Owner did interior, front compartment, engine, & underbody. Professional Detailer did the Exterior
8/2016	64,205	Replaced rear trunk light switch and installed disconnect for car shows	\$20	Owner Installed : New part came from Club member
8/2016	64,251	Replaced upper engine "dog bone" with adjustable Rodney Dickman poly version (full retail \$70)	\$50	Owner Installed : New Part was bought from Club member
9/2016	64,355	Replaced front speakers with Kenwood KFC-415C 160 Watt 4 inch by 10 inch Two Way Speaker System (retail \$150: bought on internet at	\$52	Owner Installed

**Recent Repair, Maintenance and Update Data for 1985 Fiero GT ...
 Vin Number 1G2PG3790FP268597**

Date	Mileage	Description	Cost	Performed by
		large discount)		
9/2016	64,355	Replaced tape radio with perfect match newer disc radio from replacement Radios. Color / knobs/ lighting / faceplate and equalizers perfect match. Much better sound.	\$190	Owner Installed
5/2017	64,410	Replaced window door seals (Dew Wipes) and refurbished all window mechanisms, door locks, remote mirrors, and glass tracks.	\$100	Owner installed - this is a very labor intensive job – both doors have to be completely disassembled.
2006 to 2016		Sum of recent repair, maintenance and update costs (Owner installs are parts cost only)	\$6,938	Every system referenced is working at factory specs or better