

Recent Repair, Maintenance and Update Data for 1985 Fiero GT ...

Vin Number 1G2PG3790FP268597

Date	Mileage	Description	Cost	Performed by
04/2007	50,000	New: rear brake pads/ rotors/ and both disks resurfaced / new parking brake cable installed	\$550	Davis Auto Care
04/2007	51,000	New alternator installed	\$401	Davis Auto Care
05/2007	51,500	New High Capacity Battery Installed with 3 year replacement warranty	\$85	Owner Installed
04/2008	54,000	Installed New Stainless Steel Cat Converter and Borla Stainless Steel High Performance Exhaust System (from Fiero Store)	\$900	Local Muffler Shop installed the system; good for ~ 7 HP according to Borla
04/2008	54,000	Oil change with 5-40 full synthetic motor oil / installed triple volume high capacity oil filter / greased all suspension fittings	\$50	Owner Installed
04/2009	57,000	New: spark plugs / high performance plug wires / coil / and electronic ignition module	\$150	Owner Installed : car now runs better than stock
05/2009	58,000	Installed Hypertech: High Performance Ignition Chip, 175 deg. Fan switch, and 160 deg. Thermostat (all from Fiero Store)	\$200	Owner Installed : car runs significantly better and much cooler. No more running close to engine temp red zone on very hot days; adds ~8 HP.
05/2009	59,500	New Ferrari style aluminum wheels / tires /struts / shocks / front suspension components / and alignment front and rear	\$1132	Bell Tire package deal: took ~\$400 off total of individual prices
11/2009	60,000	New High Capacity Battery Installed replaced under warranty	\$0	Owner Installed
04/2010	60,773	New air conditioning condenser / had rest of system rebuilt and converted to R134 refrigerant	\$1,316	Davis Auto Care
06/2012	61,500	Installed K & N air filter / oil change with 5-40 full synthetic motor oil / installed triple volume high capacity oil filter / greased all suspension fittings	\$80	Owner Installed : K & N air filter along with Borla exhaust and new ignition parts improved performance

Recent Repair, Maintenance and Update Data for 1985 Fiero GT ...

Vin Number 1G2PG3790FP268597

Date	Mileage	Description	Cost	Performed by
06/2012	61,500	New drivers side seat belt – safety update (Fiero Factory)	\$259	Owner Installed
06/2012	61,500	New interior headliner / visors / sun roof seals / detailed rest of interior (parts from Fiero Factory)	\$350	Owner Installed : interior now looks like new
05/2015	63,000	Cleaned and re-oiled K & N air filter / oil change with 5-40 full synthetic Mobile One motor oil / installed triple volume high capacity oil filter / new muffler clamps / greased suspension fittings	\$95	Owner Installed
05/2015	63,000	Installed two Paul Vargas rebuilt headlight motors and lubed lighting system rotating components / also realigned headlights	\$143	Owner Installed
05/2015	63,000	Installed new head light relays / fixed interior headlight switch and installed lights-up cut-off switch to save headlight motors from future wear (also functions as safety item when working near headlights)	\$100	Owner Installed
05/2015	63,300	New front brake calipers and pads / resurfaced front disks / repacked front wheel bearings / new brake fluid / and had whole braking system checked (all to spec.)	\$615	Hal's Auto Service
10/2015	64,014	Car fully detailed: interior, front compartment, engine, underbody and exterior (exterior paint cleaned, prepped, clay bared, waxed and buffed)	\$100	Owner did interior, front compartment, engine, & underbody. Professional Detailer did the Exterior
8/2016	64,205	Replaced rear trunk light switch and installed disconnect for car shows	\$20	Owner Installed : New part came from Club member
8/2016	64,251	Replaced upper engine “dog bone” with adjustable Rodney Dickman poly version (full retail \$70)	\$50	Owner Installed : New Part was bought from Club member
9/2016	64,355	Replaced front speakers with Kenwood KFC-415C 160 Watt 4 inch by 10 inch Two Way Speaker System (retail \$150: bought on internet at	\$52	Owner Installed

Recent Repair, Maintenance and Update Data for 1985 Fiero GT ...

Vin Number 1G2PG3790FP268597

Date	Mileage	Description	Cost	Performed by
		large discount)		
9/2016	64,355	Replaced tape radio with perfect match newer disc radio from replacement Radios. Color / knobs/ lighting / faceplate and equalizers perfect match. Much better sound.	\$190	Owner Installed
5/2017	64,410	Replaced window door seals (Dew Wipes) and refurbished all window mechanisms, door locks, remote mirrors, and glass tracks.	\$100	Owner installed - this is a very labor intensive job – both doors have to be completely disassembled.
2006 to 2016		Sum of recent repair, maintenance and update costs (Owner installs are parts cost only)	\$6,938	Every system referenced is working at factory specs or better